

Full Service Center 827 7th Street, Room 102 Sacramento, CA 95814 <i>M-F 8:30am - 4:30pm</i>	East Area Service Center 5229 Hazel Avenue, Suite B Fair Oaks, CA 95628 <i>M-Tu. 9:00am - 4:00pm</i>
Bradshaw Center 9700 Goethe Road, Suite A Sacramento, CA 95827 <i>M-F 8:30am - 4:30pm</i>	North Area Service Center 3331 Peacekeeper Wy., Suite 100 McClellan, CA 95652 <i>W-Th. 9:00am - 4:00pm</i>

This REQUIRED INSPECTIONS Label is intended as a guide and may not include all the required inspections for your specific permit.

Inspections 875-5381

This entire section applies for this permit

Required Inspections
Vinyl Liner or Fiberglass Pool & Spa

1. **Combination pre-gunite #501**

- Location: setbacks; utility easements
- Structural: rebar, soil, clearances
- Plumbing: filled w/ 35#, plastic gas pipe 60# test, reroute sewer or water lines with test
- Electrical: clearance to overhead lines, bonding of steel & forming shell, potting in shell, conduit to equipment, bond metal object within 5 ft., GFCI installed, light niche cord long enough.
- Safety: fence 5' high, sc gates, swing outward, alarms meet UL 2017 Standard

2. **Combination pre-deck #502**

- Final bonding of diving board, grab rails, slides, disabled access inserts and/or rope ties.
- Add common bonding grid under paved walking surface.

3. **Combination Pool Final #599**

- Structural/ Safety: sidewalks, grading, equipment location, general appearance, solar, required barriers.
- Plumbing: exposed piping leaks, APA gas value, T&P for heater (if required); secured equip., pool cover, painted PVC.
- Electrical: Overhead clearances, grounding & bonding, main panel, switch & plug locations, time clock, wire & breaker sizing, GFCI, light has low water cutoff, GFCI plugs, pool/spa lights.

4. _____

[Ø] Does not apply for this section

3 digit inspection codes preceded by #
 Req'd Insp – Vinyl Liner Fiberglass Pool Spa